

Attention: IMPORTANT SAFETY NOTICE

Voluntary product withdrawal

WAGNER Fine Spray System Model - W 650 / W 660



We have discovered that the fine spray system W 650/W 660, which has been sold since July 2007 has a manufacturing defect. The error can cause the ON/OFF switch of the device to fall out of the casing if the device is handled awkwardly, in particular if the device is allowed to fall. The result is that current-carrying parts become accessible and there is the risk of an electric shock.

If you own a W 650/W 660 fine spray system, please check the production date and serial number as indicated in figure 1. The units with a green spot on the top of the packaging or on the bottom of the device are not affected - see figure 2.

Return




Figure 1

Affected serial numbers



Do not return

Devices that have a green spot have already been checked.





Figure 2



Picture of floor of device

Devices from serial number 549411/2008, from production year 2009 et seq have been checked and do not have to be returned.

Although no damage has been incurred to date, if you do own one of the affected devices we request you to discontinue using it immediately. The affected devices have been sold widely in DIY shops, via home-shopping television and also on the Internet.

For more information, please contact us by calling: 011 267 69 69.

WAGNER is committed to providing top quality and would like to apologise to all the people concerned for the inconvenience.